



Photograph: 1	Date: 4/14/93	Taken By: Howe	Direction Facing: South
Description: Recirculation pond; former lagoon location in background			



Photograph: 2	Date: 4/14/93	Taken By: Howe	Direction Facing: Southeast
Description: Primary clarifier			



Photograph: 3	Date: 4/14/93	Taken By: Howe	Direction Facing: Northwest
Description: Location of former sludge holding pond (foreground)			



Photograph: 4	Date: 4/14/93	Taken By: Howe	Direction Facing: N/A
Description: Surface of former sludge holding pond			



Photograph: 5	Date: 4/14/93	Taken By: Howe	Direction Facing: Southeast
Description: Former outfall location (at reddish building in background) and old pier			



Photograph: 6
Date: 4/14/93
Taken By: Howe
Direction Facing: Northwest
Description: Old effluent pipe (center), and water intake pipes.



Photograph: 7	Date: 4/14/93	Taken By: Howe	Direction Facing: South
Description: Former effluent pipe and current wetlands			



Photograph: 8
Date: 4/14/93
Taken By: Howe
Direction Facing: Southwest
Description: Former effluent pipe (closest to front) with Scappoose Bay wetlands in background.



Photograph: 9

Date: 4/14/93

Taken By: Howe

Direction Facing: South

Description: Monitoring well MW1 in front of old asphalt/naptha tank structure.

Photograph: 10

Date: 4/14/93

Taken By: Howe

Direction Facing: North

Description: Monitoring well MW1 in area of potential past spillage





Photograph: 11	Date: 4/14/93	Taken By: Howe	Direction Facing: Southwest
Description: Waste pile of soils excavated near the quonset hut			



Photograph: 12	Date: 4/14/93	Taken By: Howe	Direction Facing: North
Description: Location of former burn area			



Photograph: 13	Date: 4/14/93	Taken By: Howe	Direction Facing: Unknown
Description: Old sawdust pile			